

Text basically taken from this RCgroups post

Docu for me for repairing defective FETs on the H101/H8S board (pictures). Maybe it's interesting for you guys. If one has a broken FET he could re-use a FET that's intended for inverted flying, in case he doesn't use that. Identify the defective FETs with an oscilloscope, but should be possible with a multimeter, too. If you give full throttle (in acro mode) and both PINs of one motor are 0V then the A1SHB FET for normal mode of this motor should be defect. If it's ~4V then the A0SHB FET should be defect. Maybe someone can confirm that.





From:
https://sirdomsen.diskstation.me/dokuwiki/ - **Silverware Wiki**

Permanent link:
https://sirdomsen.diskstation.me/dokuwiki/doku.php?id=h101fet&rev=1500971569

Last update: **2017/07/25 10:32**